

**From:** Info Lal Lal info@lallalwindfarms.com.au   
**Subject:** RE: Incident Shadow Flicker  
**Date:** 23 June 2025 at 1:26 pm  
**To:** [REDACTED] Info Lal Lal info@lallalwindfarms.com.au

IL

Hi Owen.

Your reference number for shadow flicker incident recorded over the weekend is LLWF-ELA-23062025.1 – we did look at the satellite images from the date and time of your last submitted shadow flicker incident however without actual recorded evidence showing shadow flicker from the residence it's difficult to ascertain a response. If you do have any recordings, please be sure to provide.

Regards

---

**From:** [REDACTED]  
**Sent:** Saturday, 21 June 2025 6:12 PM  
**To:** Info Lal Lal <info@lallalwindfarms.com.au>  
**Cc:** [REDACTED]  
**Subject:** Incident Shadow Flicker

**ATTENTION:** This originated outside of RES. Do not click links or open attachments unless you recognise the sender and know the content is safe. If you suspect this to be a malicious email, please report it using the **Phish Alert Button**.

Dear Nathan

Please acknowledge and provide the details of You recording the attached in "LLWF complaints/incident register" within forty-eight (48) hours

Regards

Owen

NOTICE TO RECIPIENT: This e-mail is meant for only the intended recipient of the transmission, and may be a communication privileged by law. This e-mail, including any attachments, contains information that may be confidential, and is protected by copyright. If you received this e-mail in error, any review, use, dissemination, distribution, or copying of this e-mail is strictly prohibited. Please notify us immediately of the error by return e-mail and please delete this message from your system. Any communication of a personal nature in this e-mail is not made by or on behalf of any RES group company. E-mails sent or received may be monitored to ensure compliance with the law, regulation and/or our policies. Thank you in advance for your cooperation.