

From: Owen ~~owen@lallalwindfarms.com.au~~
Subject: Shadow Flicker Observation – 27 June 2026
Date: 27 June 2026 at 5:17 pm
To: Info Lal Lal info@lallalwindfarms.com.au

Dear Sir/Madam,

I write to record an observation of shadow flicker associated with the Lal Lal Wind Farm.

On 27 June 2026, shadow flicker was observed affecting the amenity of the dwelling at J14aa, being 308 Elaine-Mount Mercer Road, which I occupy.

The shadow flicker became apparent at approximately 4:38 pm and gradually weakened from approximately 4:53 pm.

This email is provided for record purposes only. Please record this observation within your incident and complaints register.

Kind regards,

Owen Robert

From: Owen [REDACTED]
Subject: Shadow Flicker Observation -- 30 June 2026
Date: 30 June 2026 at 6:12 pm
To: Info Lal Lal info@lalalwindfarms.com.au

Dear Sir/Madam,

I write to record an observation of shadow flicker associated with the Lal Lal Wind Farm.

On the evening of 30 June 2026, shadow flicker was observed affecting the amenity of the dwelling at J14aa, being 308 Elaine Mount Mercer Road, which I occupy.

The shadow flicker was first noticed at approximately 4:45 pm under partly cloudy conditions and gradually diminished over time until it was no longer observable.

This email is provided for record purposes only. Please record this observation within your incident and complaints register.

Kind regards,

Owen Robert

From: Owen owenrobert@lallalwindfarms.com.au
Subject: Shadow Flicker Observation – 12 July 2026
Date: 12 July 2026 at 5:16 pm
To: Info Lal Lal info@lallalwindfarms.com.au

Dear Sir/Madam,

I write to record a further observation of shadow flicker associated with the Lal Lal Wind Farm.

On 12 July 2026, shadow flicker was observed affecting the amenity of the dwelling at J14aa, being 308 Elaine–Mount Mercer Road, which I occupy.

The shadow flicker became apparent at approximately 4:58 pm and gradually diminished over time until it was no longer observable.

This email is provided for record purposes only. Please record this observation within your incident and complaints register.

I also refer to my previous emails dated 27 June 2026, 30 June 2026 and 9 July 2026 recording shadow flicker observations. To date, I have not received any acknowledgement or response. I would appreciate confirmation that each observation has been recorded within your incident and complaints register, together with an update regarding those notifications.

Kind regards,

Owen Robert

From: Owen ~~Owenrobert1978@gmail.com~~
Subject: Further Shadow Flicker Observations – 17 and 18 July 2026
Date: 19 July 2026 at 6:46 pm
To: Info Lal Lal info@lallalwindfarms.com.au

Dear Sir/Madam,

I write to record two further observations of shadow flicker associated with the Lal Lal Wind Farm.

On Friday, 17 July 2026, and again on Saturday, 18 July 2026, shadow flicker was observed affecting the amenity of the dwelling at J14aa, being 308 Elaine-Mount Mercer Road, which I occupy.

On each occasion, the shadow flicker became apparent shortly before 5:00 pm and continued for approximately 10–15 minutes before gradually diminishing.

This email is provided for record purposes only. Please record these observations within your incident and complaints register.

I also refer to my previous shadow flicker notifications dated 27 June 2026, 30 June 2026, 9 July 2026 and 12 July 2026. To date, I have not received any acknowledgement or response to any of those notifications.

I would appreciate confirmation that each of these observations, including those recorded in this email, has been entered into your incident and complaints register, together with an update regarding my previous notifications.

Kind regards,

Owen Robert